

Amendments to the claims:

1. (currently amended) A hand power tool, comprising a housing; and a pistol-shaped handle which is supported on said housing displaceably substantially in a direction of a longitudinal axis of the hand power tool, further comprising a guide provided in said housing and extending substantially parallel to said longitudinal axis and displaceably supporting said handle and mounting means for fixing said handle in selected positions on said housing, wherein said guide and said handle are substantially groove-shaped and tongue-shaped, and further comprising contact elements provided on said handle and on said housing and located in regions which contact one another for directing current flow through electrical components in said handle and said housing.

2. (canceled)

3. (canceled)

4. (canceled)

5. (currently amended) A hand power tool as defined in claim [[4]] 1, wherein said contact elements include a plurality of contact rails arranged in said guide of said housing and a plurality of contact points arranged on said handle and contacting said contact rails.

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.